AC NO: 20-104

DATE: 4/12/78



ADVISORY CIRCULAR

DEPARTMENT OF TRANSPORTATIONFEDERAL AVIATION ADMINISTRATION

SUBJECT: REVISED POWERPLANT ENGINEERING REPORT NO. 3A. STANDARD FIRE TEST APPARATUS AND PROCEDURE (FOR FLEXIBLE HOSE ASSEMBLIES)

1. <u>PURPOSE</u>. This advisory circular announces the availability of revised copies of Power Plant Engineering Report No. 3A, Standard Fire Test Apparatus and Procedure (for Flexible Hose Assemblies). The revised . report presents data on currently available acceptable burners which may be used as replacements for the originally specified Lennox, Model OB-32 oil burner which is no longer available.

2. INSTRUCTION FOR ORDERING.

- a. Copies may be ordered, free of charge, from:
 - U. S. Department of Transportation Publications Section, M-443.1 Washington, D. C. 20591
- b. Identify the report as:

Power Plant Engineering Report No. **3A**Standard Fire Test Apparatus and Procedure
(for Flexible Hose Assemblies) Revised March **1978**

G. A. MCKAY

Acting Director

Flight Standards Service

Initiated by: AFS-140